Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 1
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1023
Description: Outside Powerblock – Aux Turbine Storage Area. View of a 55-gallon used oil storage container on the left (approximately ½ full) and a 55-gallon PCB-containing capacitors storage container (approximately ¼ full). The used oil storage container is structurally sound and labeled with the words “used oil.”

Photo Number: 2
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1023
Description: Outside Powerblock – Aux Turbine Storage Area. View of the label on the used oil storage container shown on the left in Photo 1.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 3
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1023
Description: Outside Powerblock – Aux Turbine Storage Area. View of the label on the PCB-containing capacitors storage container shown on the right in Photo 1.

Photo Number: 4
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1029
Description: Powerblock SAA for First Shift. View of (left to right): oily rags storage container (red), used oil filter draining container (magenta), used oil filters storage container (blue), bags with oily rags, used oil storage container (red).

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 5
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1029
Description: Powerblock SAA for First Shift. View of the used oil filters storage container shown in Photo 4. Used oil filters are hot drained only, then disposed as used oil. The used oil filters storage container is structurally sound and labeled with the words "used oil filters."

Photo Number: 6
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1029
Description: Powerblock SAA for First Shift. View of the used oil filter draining container shown in Photo 4. The used oil filter draining container is a used oil storage container. The used oil storage container is structurally sound, but not labeled with the words "used oil."

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 7
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1046
Description: Powerblock SAA for First Shift. View of the used oil filter draining container (used oil storage container) shown in Photo 6, after facility representatives labeled the container with the words “used oil.”

Photo Number: 8
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1029
Description: Powerblock SAA for First Shift. View of the 55-gallon used oil storage container shown in Photo 4. The used oil storage container is approximately ½ full, structurally sound, and labeled with the words “used oil.”

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 9
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. View of four, stacked five-gallon containers behind the 55-gallon used oil storage container shown in Photo 4. The bottom five-gallon container is labeled with the words "used oil." However, the top five-gallon container (with the funnel) holds approximately two gallons of used oil and is not labeled with the words "used oil."

Photo Number: 10
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. View of the bottom five-gallon container shown in Photo 9, with the words "used oil."

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 11
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. View of the top five-gallon used oil storage container shown in Photo 9. The used oil storage container is structurally sound and holds approximately two gallons of used oil, but is not labeled with the words “used oil.”

Photo Number: 12
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. Another view of the top five-gallon used oil storage container shown in Photo 9. The used oil storage container is structurally sound and holds approximately two gallons of used oil, but is not labeled with the words “used oil.”

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 13
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. Another view of the top five-gallon used oil storage container shown in Photo 9. The used oil storage container is structurally sound and holds approximately two gallons of used oil, but is not labeled with the words “used oil.”

Photo Number: 14
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1031
Description: Powerblock SAA for First Shift. Another view of the top five-gallon used oil storage container shown in Photo 9. The used oil storage container is structurally sound and holds approximately two gallons of used oil, but is not labeled with the words “used oil.”



Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 15
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1046
Description: Powerblock SAA for First Shift. View of the unlabeled, five-gallon used oil storage container shown in Photos 11-14, after facility representatives labeled the container with the words “used oil.”

Photo Number: 16
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1046
Description: Powerblock SAA for First Shift. View of a storage container for empty aerosol cans. The storage container holds a few aerosol cans, and all appear to be RCRA-empty.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 17
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1041
Description: Powerblock SAA for Second Shift. View of a 55-gallon used oil storage container. The used oil storage container is approximately ½ full, structurally sound, and labeled with the words “used oil.”

Photo Number: 18
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1041
Description: Powerblock SAA for Second Shift. View of a five-gallon used oil storage container adjacent to the 55-gallon used oil storage container. The five-gallon used oil storage container holds approximately two gallons of used oil, is structurally sound, but is not labeled with the words “used oil.”

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 19
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1041
Description: Powerblock SAA for Second Shift. Another view of the unlabeled, five-gallon used oil storage container shown in Photo 18.

Photo Number: 20
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1050
Description: Powerblock SAA for Second Shift. View of the five-gallon used oil storage container shown in Photo 18, after facility representatives added the words “used oil” to the container.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 21
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1043
Description: Powerblock SAA for Second Shift. View of a storage container (metal trash can) for storage of empty aerosol cans. The storage container holds approximately 20 empty aerosol cans, and all appear to be RCRA empty.

Photo Number: 22
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1044
Description: Powerblock SAA for Second Shift. View of the labeling on top of the empty aerosol cans storage container shown in Photo 21.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 23
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1058
Description: Powerblock, SAA Site R. One, 35-gallon container holding approximately 15 gallons of hazardous laboratory waste (mixed solvent and water). Facility identifies this container as a satellite accumulation container from the Water Lab.

Photo Number: 24
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1059
Description: Powerblock, SAA Site R. Another view of 35-gallon container holding approximately 15 gallons of hazardous laboratory waste (mixed solvent and water). Facility identifies this container as a satellite accumulation container from the Water Lab. However, container may not be near the point of generation.



Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 25
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1107
Description: Powerblock, SAA Site R. View of the path from the point of generation (Water Lab) to the 35-gallon container. Technician must travel from lab, out the far doorway.

Photo Number: 26
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1108
Description: Powerblock, SAA Site R. View of the path from the point of generation (Water Lab) to the 35-gallon container. After passing through the doorway shown in Photo 25, technician must travel through the doorway beneath the exit sign.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 27
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1108
Description: Powerblock, SAA Site R. View of the path from the point of generation (Water Lab) to the 35-gallon container. View of the 35-gallon container from the doorway beneath the exit sign shown in Photo 26.

Photo Number: 28
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1122
Description: Scrubber Lab. View of areas identified by the facility as SAA 01 (left) and SAA 02 (right). Point of generation is the Scrubber Lab inside the building.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 29
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1122
Description: Scrubber Lab. Close-up view of the area identified as SAA 01 shown in Photo 28. One, 35-gallon container holding approximately four gallons of inorganic hazardous waste.

Photo Number: 30
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1122
Description: Scrubber Lab. Close-up view of the area identified as SAA 02 shown in Photo 28. One, 35-gallon container holding approximately 18 gallons of organic hazardous waste.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 31
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1126
Description: Scrubber Lab. View of the "day cans" used to accumulate hazardous waste inside the Scrubber Lab. Hazardous waste is emptied daily into the SAA 01 and/or SAA 02 containers.

Photo Number: 32
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1133
Description: FDG Pump House SAA. View of a 35-gallon container approximately ½-full with aerosol cans. One aerosol can is not RCRA-empty (approximately ¼-full). The aerosol cans hold/held heptane and alcohol cleaning solvent (likely D001 characteristic hazardous waste). Because of this, the 35-gallon container is an open satellite accumulation container.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 33
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1133
Description: FDG Pump House SAA. View inside of the 35-gallon satellite accumulation container shown in Photo 32.

Photo Number: 34
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1656
Description: FDG Pump House SAA. View of a new, closed aerosol cans satellite accumulation container placed in this area by facility representatives to replace the previously-open satellite accumulation container.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 35
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1333
Description: Paint Building SAA. View of the area identified by facility personnel as the Paint Building SAA. One, 16-gallon hazardous waste paint-related material storage container (holding approximately two gallons); one 16-gallon nonhazardous water-based paint storage container (holding approximately 12 gallons); and one container for RCRA-empty aerosol cans. The hazardous and nonhazardous paint wastes are generated inside the adjacent Paint Building.

Photo Number: 36
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1339
Description: Fuel Lab SAA. View of the area identified by facility personnel as the Fuel Lab SAA. One, 16-gallon hazardous waste solvent storage container (holding approximately 10 gallons); one empty container for aerosol cans; and one 35-gallon used oil storage container (holding approximately one gallon). The hazardous and nonhazardous wastes are generated inside the Fuel Lab building.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 37
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1339
Description: View of the Fuel Lab building from the area identified as the Fuel Lab SAA. The area identified as the Fuel Lab SAA may not be near the point of generation.

Photo Number: 38
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1415
Description: Auto Bay. View of a 500-gallon used oil storage tank. The used oil storage tank is structurally sound and labeled with the words “used oil.”

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 39
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1431
Description: Railroad SAA. View one, 16-gallon satellite accumulation container holding hazardous waste solvents (approximately full); and one, 16-gallon container holding nonhazardous paint wastes (approximately 10 gallons) in the Railroad SAA. The satellite accumulation container is structurally sound, labeled to identify its contents, closed, and near the point of generation.

Photo Number: 40
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1431
Description: Railroad SAA. View of one, 55-gallon used oil storage container in the Railroad SAA. The used oil storage container is structurally sound and labeled with the words “used oil.” One of the one-gallon containers to the right holds approximately ¾ gallons of used oil, and is not labeled with the words “used oil.”

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Photo Number: 41
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1431
Description: Railroad SAA. View of two, one-gallon containers shown in Photo 40. One is empty, the other holds used oil (approximately ¾ full). The used oil storage container is structurally sound, but not labeled with the words “used oil.”

Photo Number: 42
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1433
Description: Railroad SAA. View of the unlabeled, one-gallon used oil storage container shown in Photo 41 after facility representatives labeled the container with the words “used oil.”

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 43
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1520
Description: 180-day Hazardous Waste Storage Area. View of one of two, 20-cubic-yard rolloff containers for nonhazardous oily cleanup debris and rags storage.

Photo Number: 44
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1520
Description: 180-day Hazardous Waste Storage Area. View of one of two, 20-cubic-yard rolloff containers for nonhazardous oily cleanup debris and rags storage.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 45
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1524
Description: 180-day Hazardous Waste Storage Area. View of the aerosol can puncturing unit in the hazardous waste storage area.

Photo Number: 46
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1525
Description: 180-day Hazardous Waste Storage Area. View of punctured, drained aerosol cans in the hazardous waste storage area. Punctured, drained cans are recycled as scrap steel. Liquids drained from the cans are accumulated in a satellite accumulation container.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 47
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1525
Description: 180-day Hazardous Waste Storage Area. View of aerosol cans waiting puncturing. Per facility representatives, this volume represents approximately two weeks of accumulation.

Photo Number: 48
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1528
Description: 180-day Hazardous Waste Storage Area. View of the SAA for aerosol can puncturing waste. The satellite accumulation container holds approximately 50 gallons of hazardous waste, and is structurally sound, closed, at near the point of generation.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 49
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1531
Description: 180-day Hazardous Waste Storage Area. View of the two, hazardous waste storage containers in the hazardous waste storage area at the time of the CEI. One, 20-gallon container holding D009 characteristic mercury debris (dated 3/9/12); and one, 55-gallon container holding D008 characteristic lead-contaminated debris (dated 11/21/11). Both hazardous waste storage containers are structurally sound, closed, and labeled with the words “hazardous waste.”

Photo Number: 50
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1531
Description: 180-day Hazardous Waste Storage Area. Close-up view of the mercury debris hazardous waste storage container shown in Photo 49.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 51
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1531
Description: 180-day Hazardous Waste Storage Area. Close-up view of the lead-contaminated debris hazardous waste storage container shown in Photo 49. Container not labeled with the words “hazardous waste.”

Photo Number: 52
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1534
Description: 180-day Hazardous Waste Storage Area. Nonhazardous wastes (e.g., grease, nonhazardous waste resin, nonhazardous paint) in storage at the time of the CEI.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 53
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1536
Description: 180-day Hazardous Waste Storage Area. Two, 55-gallon containers holding odd-shaped and/or broken universal waste lamps. The containers are managed as universal waste lamps storage containers. The universal waste lamps storage containers are structurally sound, closed, labeled with the words "universal waste lamps," and dated 4/5/12 and 4/9/12.

Photo Number: 54
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1536
Description: 180-day Hazardous Waste Storage Area. Close-up view of the labeling on one of the two, 55-gallon universal waste lamps storage containers shown in Photo 53.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 55
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1544
Description: 180-day Hazardous Waste Storage Area. View of the 15 universal waste lamps storage building. All are structurally sound, closed, labeled with the words “universal waste lamps,” and dated (earliest date is 2/14/12).

Photo Number: 56
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1544
Description: 180-day Hazardous Waste Storage Area. Close-up view of the labeling and closed containers for two of the 15 universal waste lamps storage containers shown in Photo 55.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 57
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1443
Description: Solid Waste Landfill. View of the sign posted at the solid waste landfill, listing types of waste prohibited from disposal.

Photo Number: 58
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1450
Description: Solid Waste Landfill. View across the top of the solid waste landfill. Bottom ash is used as daily cover.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 59
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1449
Description: Solid Waste Landfill. View of current day's solid waste added to the landfill unit. The solid waste consists of non-asbestos brake pads and general debris.

Photo Number: 60
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1458
Description: Ash Disposal Area. View of the ash disposal area, used for land disposal of unsold fly ash, bottom ash, and scrubber waste (calcium sulfate).

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 61
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1458
Description: Ash Disposal Area. Another view of the ash disposal area, used for land disposal of unsold fly ash, bottom ash, and scrubber waste (calcium sulfate).

Photo Number: 62
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1723
Description: View of APS Substation onsite, from SRP parking lot.

Original photos transferred, without modification, to CD on 5/14/2012 by John Dixon

Salt River Project Navajo Generation Station
Page, AZ

Photo Number: 63
Photographer: John Dixon
Camera: Sony Cybershot DSC-W370
Date: 4/16/2012
Time: 1723
Description: View of APS Substation onsite, from SRP parking lot.

END OF PHOTOGRAPHIC DOCUMENTATION